



www.nuvitechemical.com

800.394.8351 • 516.935.4000



Nulmage

CLEANER & DEBUGGER FOR POLISHED METAL

For cleaning stubborn bug residue, perfect for touch-ups in between polishing



GENERAL CLEANING

1. Pour a small amount of **Nulmage** onto a flannel polishing cloth.
2. Apply to surface, wiping on gently to avoid scratching from surface soils & dust.
3. Gently spread material over target polish area.
4. Rub until **Nulmage** is removed.
5. Slight haze will remain, allow to dry.
6. After haze has dried completely, polish away to bright shine with clean cotton flannel polishing cloth.



STUBBORN BUG REMOVAL

1. Wet bug spot with **Nulmage**.
2. Spread material on area around bug while **Nulmage** soaks bug material.
3. After a few seconds, rub away bug residue.
4. Keep any remaining bug residue wet & soaking.
5. Remove with gentle rubbing.
6. Repeat until bug spot is disappeared.

**Product dilutions are determined by extent, condition & soil type.*

When using any NUVITE product, please refer to appropriate procedures and recommendations for use and equipment, or contact a NUVITE technician for more information, unique applications and special requirements.

QUESTIONS? NUVITE technicians have the answers 800.394.8351